

CEI
SN 28604N

CANNON ELECTRONICS
BASIC SERVO ASSEMBLY INSTRUCTIONS


9/21/71
540-E
PARTS LAYOUT
1974

The following instructions apply to all servos. Follow applicable instructions if one or two P.C. boards are used.

1. Use a pencil type low wattage soldering iron, 30 to 47-1/2 watts (maximum).
2. To assemble P.C. board (s) first position board, metal side down, so that hole arrangement corresponds with assembly illustration. Locate desired mounting holes, insert wire leads of part through holes until part is positioned as close to board as possible. Bend wire leads over solidly against solder lands on bottom of board to hold part firmly in position. Clip off excess lead length, leaving at least 1/16" to hold part in place. It is extremely important on this servo that leads be as flat as possible against lands, or cover may not fit. Also, leads must not extend beyond edge of land to which it connects.
3. Assemble and solder parts on board (s) as shown. Use as little solder as possible to reduce bulk on back side of board.
4. Cut short wires to lengths shown. Remove 3/32" insulation from each wire end, except remove 1/2" insulation from end of wire which connects to motor ground.
5. Solder wires to Board No. 1, then solder other end of wires (except motor) to Board No. 2. (On servos where two boards are used).
6. Assemble servo plug and cable. Cut each wire end to proper length to attach to P.C. board (s) (minimum 1/2" for any wire). Solder wires to P.C. board (s).
7. On MODEL 540 servos, cut the prefabricated cable assembly so that wires are 10" long.
8. On some servos, it will be necessary to assemble pot wiper to wiper plate as shown.
9. On C-E1 and C-E3 servos, install wiper assembly in pot housing so that contacts face end of servo. Press firmly on plastic pot wiper center plate while holding output shaft until pot wiper assembly is firmly seated.
10. If necessary, position motor and feedback pot as shown on drawing. Do not tighten pot screws.
11. Clean solder flux from boards with lacquer thinner. Inspect both sides of board (s) very carefully with an eye loupe to make certain all parts are correctly installed, as close to board (s) as possible, that parts will not touch when boards are brought together, and that no solder shorts exist on back sides of boards.
12. Using a fine, flat file or fine sandpaper block, very carefully remove excess material (solder, etc.) that project from soldered side of board. It is important that outsides of P.C. board (s) be as flat as possible to permit installation of servo cover. Clean and recheck to be sure all joints are well soldered. Touch up where necessary.
13. Position boards facing each other with solder sides out. Connect green, yellow and brown wires to correct tabs on feedback pot.
14. Solder white and black leads to motor. Be sure long bare end of ground wire is soldered to both tabs as shown.
15. Plug servo into receiver and check operation. Center servo to your Tx as explained on drawing.
16. Dress wires for best fit and fit each board vertically, one into each side of servo. Be sure parts do not touch, then install cover with screws. Grommet should fit into cover slot.


540-E SERVO

BLACK
8 OHM
MOTOR



TO REVERSE SERVO
DIRECTION, REVERSE
MOTOR WIRES AND
GRN & BLK WIRES
TO POT. RECENTER
SERVO

SCREW AND
FIBER WASHER
(2 REQ)



1/8 WATT RESISTORS
UNDER I.C. INSTALL
THESE FIRST

1-1/8"
YEL
TO
POT

INSTALL DIODE
WITH BAND UP

EXCEPT FOR C3,
INSTALL ALL
TANTALUM CAPS
WITH RED END UP

TO CENTER SERVO,
REMOVE OUTPUT ARM
RETAINING SCREW,
INSERT SMALL
JEWELERS SCREW-
DRIVER INTO HOLE
IN TOP OF OUTPUT
SHAFT AND ROTATE
SCREWDRIVER UNTIL
CORRECT CENTER
IS OBTAINED.

STD: 8" CABLE BEFORE TWIST
T.B.: 7" CABLE BEFORE TWIST


SEE CABLE DRAWING FOR
DETAILS OF SERVO PLUG
AND CABLE ASSEMBLY.

REDUCE C6 TO
DECREASE SERVO
DEAD BAND


INCREASE R3 TO
DECREASE THROW

1-1/8" BLK TO PLUG
1-1/8" BRN TO POT
OR TO PLUG
1-1/8" RED TO PLUG
1-1/8" GRN TO POT


CANNON ELECTRONICS
C-E1 SERVO



6/15/74



* SMALLER VALUE FOR
 MINIMUM DEAD BAND
 ** VARY VALUE TO INCREASE
 OR DECREASE SERVO
 THROW




SCHEMATIC VARIATION
 FOR 180° SERVO

1974 3-WIRE

5/21/74

SERVO PLUG AND CABLE ASSEMBLY (ALL SERVOS)



WIRES 8" TO START

1. SOLDER WIRES TO PLUG.
2. INSTALL 4 SHRINK TUBINGS AT PLUG END.
3. TWIST WIRES.
4. INSTALL SINGLE SHRINK TUBING AT POSITION SHOWN.
5. SLIDE ON GROMMET
6. UNTWIST END WIRES
7. CUT OR AND BLK WIRES 1/4" SHORTER THAN RED WIRE.
8. CONNECT WIRES TO P.C. BOARD