


## **FM DATA SHEETS**

#17-R/C CONTROL SYSTEMS







SES A YAWING ACTION OPPOSITE TO THE DESIRED TURN. THIS IS CAUSED BY THE MORE PRONOUNCED DRAG OF THE DROOPING AILERON.

SEVEN CHANNELS WOULD BE DESIRABLE TO OPERATE A FULL COMPLEMENT OF CONTROLS, RUDDER, ELEVATOR, AILERON AND ENGINE SPEED. HOWEVER, WITH THE EXIST-ING FIVE CHANNEL EQUIPMENT A COMPLETE CONTROL SYS- TRY ONE OF THE ABOVE FOR THOSE ADDED POINTS IN "SLOWROLLS", "IMMELMANNS". MAKE TURNS WITHOUT LOOSING ALTITUDE, FLY INVERTED WITHOUT "FALLING OUT" AND MAKE SUPERB "CUBAN EIGHTS."

BOB COON