







ERROR VOLT
TO FEEDBACK SERVO




VOLTAGE DIVIDER
TO AUDIO XFMER SECONDARY



CH #	C ₁	C ₂	R	
1	.04	.0033	2.7K ✓	AIL
2	.025	.0015	3.3K ✓	RUD EL
3	.015 + .0022 .001	.0012	3.9K ✓	ELEV RUD
4	.012	560 + 200pF	4.7K ✓	MOT & AUX

Audio
on Col. 4.5V -
2N217

LOCKED
SYNCHRONOUS
DETECTOR




31 JAN 1965
PROJ 4-12-65



COMPONENT SIDE VIEW

CCS TOP DECK

AUDIO
BOTTOM
TO DECK



SUPER HET
TEST POINT

BY.....DATE.....

CHKD. BY.....DATE.....

SUBJECT DECODE CARD

SHEET NO. 1 OF 1

JOB NO. 254

OK

